

INFORMATION FOR OUR TENANTS



REPLACEMENT OF SMOKE ALARMS BY



Dear Tenants,

In accordance with DIN 14676-1, the smoke alarms installed in your flat must be replaced at the latest after 10 years, and after six months following initial operation.

Work to replace the smoke alarms, which we have commissioned Techem Energy Services GmbH to carry out, is now in hand.

Techem will contact you to offer you an appointment for replacing the smoke alarms. Please take up this offer to enable the work to be carried out without a hitch. You can also arrange for a person you trust to grant access to your flat. Replacing the smoke alarms will not incur any costs for you.

Please note that the smoke alarms must also be replaced if individual units have been replaced in your flat ahead of schedule for repairs to be carried out.

Please do not hesitate to contact us if you have any questions.

Many thanks

Hallesche Wohnungsgesellschaft mbH



Hallesche Wohnungs-
gesellschaft mbH
Hansering 19
06108 Halle (Saale)

Telefon: 0345 / 527 0
Fax: 0345 / 527 2030
E-Mail: hwg@hwgmbh.de
www.hwgmbh.de

27. April 2023